

AUREUS 28 Firmware Changelog

FW 2.6.6 - 2020.10.09

Release version

FW 2.7.2 - 2020.12.21

Minor Bug fix associated with fader flip on PLAY and ST21/22 channels

FW 2.7.4 - 2021.01.12

This update prevents the mixer from locking up in certain circumstances.

FW 2.7.7 - 2021.02.23

Removes redundant controls from remote and improves boot time.

FW 2.10.5 - 2021.08.11

Improvement to fader movement.

FW 2.20.1 - 2021.12.03

Minor improvement to channel gain consistency.